

Trouble shooting in tapping


Tapping is a complex process and often the last machining operation performed on the workpiece. Therefore incorrect or faulty tapping can compromise the quality of the entire workpiece.


Numerous factors influence the process:

- *Cutting parameters*
- *Drilling parameters*
- *Lubrication*
- *Machine conditions.*

The choice of correct tool is paramount in order to obtain high quality threads.

The following table summarizes the most common problems encountered during tapping and their possible solutions.

<i>Problem</i>	<i>Solution</i>	<i>How tap or thread is damaged</i>
<p><i>Chipped teeth on tap</i></p>	<ul style="list-style-type: none"> ➤ <i>Choose correct tap, with lower rake angle or longer chamfer.</i> ➤ <i>Reduce cutting speed</i> ➤ <i>Check drilled hole size is not too small</i> ➤ <i>Check tap alignment</i> 	
<p><i>Excessive tap wear</i></p>	<ul style="list-style-type: none"> ➤ <i>Improve quantity and quality of lubrication</i> ➤ <i>Use tap with more relief, longer chamfer, higher rake angle and/or coating</i> 	
<p><i>Chip clogging flutes</i></p>	<ul style="list-style-type: none"> ➤ <i>Choose correct tap for specific application (spiral flute angle suitable for depth of hole, rake angle and relief suitable for material)</i> ➤ <i>Increase lubricant pressure</i> 	

<p>Poor finish on threaded workpiece</p>	<ul style="list-style-type: none"> ➤ Check wear of tap. Resharpen or change ➤ Improve quantity and quality of lubrication ➤ Choose suitable tap (Rake angle and relief angle) 	
<p>Build-up edge or sticking</p>	<ul style="list-style-type: none"> ➤ Use a suitable tap with correct rake angle and relief angle ➤ Increase the cutting speed ➤ Choose a correct coating ➤ Improve quantity and quality of lubrication 	
<p>Crater wear</p>	<ul style="list-style-type: none"> ➤ Choose a tap with higher hardness and/or appropriate coating ➤ Improve quantity and quality of lubrication 	
<p>Tap breakage</p>	<ul style="list-style-type: none"> ➤ Increase drilled hole size ➤ Check wear of tap. Resharpen or change ➤ Check drilled hole is not too shallow ➤ Reduce cutting speed ➤ Use tapping attachment with safety clutch 	
<p>Oversized thread</p>	<ul style="list-style-type: none"> ➤ Check tap tolerance is suitable for requested nut tolerance ➤ Choose appropriate tap for application (rake angle and relief suitable for material) ➤ Reduce feed rate or use tap attachment with compensation ➤ Reduce cutting speed ➤ Verify tap-hole alignment and workpiece fixture 	

<p><i>Undersized thread</i></p>	<ul style="list-style-type: none"> ➤ <i>Check tap tolerance is suitable for requested nut tolerance</i> ➤ <i>Increase drilled hole size</i> ➤ <i>Check wear on tap. Resharpener or change</i> ➤ <i>Choose appropriate tap (higher rake angle and relief)</i> ➤ <i>Improve quantity and quality of lubricant</i> 	
<p><i>Richiesta di potenza eccessiva sul mandrino</i></p>	<ul style="list-style-type: none"> ➤ <i>Increase drilled hole size</i> ➤ <i>Check wear on tap. Resharpener or change</i> ➤ <i>Choose appropriate tap (higher rake angle and relief)</i> ➤ <i>Improve quantity and quality of lubricant</i> 	